

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																														
TECH.		DISOB.		NEG NCE		INEXP NCE		MISCEL.		INSTRUCT.		FLT CONTR.		OTHERS		PRIMARY		FL CONTRS.		MOV SURFS.		STAB SURFS.		W STRUTS		LAND GEAR		FLOATS		FUSE OR HULL		TAIL SKID OR W.		ENGINE MOUNT		MISCEL.		UND TD		PRIMARY		FUEL SYS.		COOL SYS.		IGNIT. SYS.		LUB'N SYS.		ENG STR		AIRSCREW A.		ENG. CONTRS.		MISCEL.		UNSD TD		PRIMARY	
PILOT										OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																															
CAUSES OF ACCIDENTS																																																													
UNIT 8 RD Winnipeg, Man.								COM.								PLACE Stony Mountain, Manitoba Near Parkdale, Man.								DATE 3-12-41				TIME 1430																																	
A/C TYPE Tiger Moth								No. 5918								CRASH CAT. "A"				SE		ME		DAY		NIGHT																																			
NAME Rhodes, A.D.								F NK F/O		No 02398		DUTY P		INJURIES Slightly injured								SERIOUS FATAL INJURY																																							
																				CARD SERIAL NO.																																									
TYPE A/F & ENGINE				No.				EXTENT OF DAMAGE				REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																											
T. Moth				5918				Total										INST.		NIGHT		ON TYPE				TOTAL				LAST 6 MOS																															
Gypsy M				N.A				Total														DUAL SOLO				DUAL SOLO																																			
M.K.I.																						553																																							
SIGNAL No. & DATE								UNIT No & DATE								COM No & DATE								REPORT				FILE				DATE																													
0592 3-12																																																													
& 0597								NATURE OF ACCIDENT																																																					
CATEGORY		TYPE OF ENGINE		TYPE OF A/C		MISCELLANEOUS CAUSES		STAGE OF FLIGHT																																																					
D		A		2		UNSD TD		FLIGHT																																																					
C		B		1		PRIMARY		TAKE-OFF																																																					
18		17		16		LANDING		FLIGHT																																																					
15		14		13		TAXIING		FLIGHT																																																					
12		11		10		PRIMARY		FLIGHT																																																					
9		8		7		UNSD TD		FLIGHT																																																					
6		5		4		OTHER		FLIGHT																																																					
3		2		1		AL'S SURF.		FLIGHT																																																					
19		18		17		DRKNS.		FLIGHT																																																					
16		15		14		WEATHER		FLIGHT																																																					
13		12		11		INSTS.		FLIGHT																																																					
10		9		8		HAND Q.		FLIGHT																																																					
7		6		5		PRIMARY		FLIGHT																																																					
4		3		2		UNSD TD		FLIGHT																																																					
1		19		18		PRIMARY		FLIGHT																																																					

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Test flight

OR COMMANDING OFFICER'S REPORT:

Investigating Officer's Report.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: 5/12/41

10011/1002/1004

Pilot took off on test flight of Composition:-

newly rigged Aircraft immediately behind another Aircraft and believing Flt.Lt. J.D. Fitzsimmons. the slipstream to be cause of unusual behavior. Having attempted landing

RECOMMENDATIONS:

several times, managed to reach a safe height and abandoned Aircraft. (a) That a routine check on this alignment be instituted on all new or overhauled aircraft of this type and (b) That the contractor be requested to make further recommendations.

PRIMARY CAUSE:

(NOTE: I understand that such a misalignment was encountered here some months ago and that it was discovered that the spar ends were incorrectly fitted into fittings.)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Possibility of un-noticed angular mis-alignment of one or both sections of tail plane with respect to fuselage viewed along its axis, which would alter from normal, the angle of incidence of the section of the tail plane, thus affecting the controllability of the Aircraft.

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft crashed.

(Pilot abandoned aircraft by parachute)

RECORDED BY

DATE

CHECKED BY

DATE