

CASPIR Aircraft Accident Cards

Serial:	AL109
Title:	Curtiss Kittyhawk Mk. I serial:AL109 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1942-August-08. Kittyhawk s/n AL109. This accident involved 1 person. Mcduff DM
Keywords:	RCAFKittyhawk ,AL109,14 Sqn,14 Squadron,Aerodrome,1942-August-08,McduffRCAF L20
Created:	1942-08-08
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000961#AL109

TYPE OF A/C		CAUSES OF ACCIDENTS										ENGINE FAILURE													
UNIT		COM.		PLACE		DATE		TIME		H.Q. FILE		A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT	
14 SQUADRON (F)		WAC		LA		C-2-32		1145		100-AL109		KITTYHAWK		AL109		C 4		X							
SEA ISLAND																									
NAME		RANK		No.		DUTY		INJURIES		SERIOUS		FATAL		INJURY		CARD SERIAL No.									
MCQUEEN, J.H.		P.O.		J11967		P.P.		UNINJURED																	
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS					
KITTYHAWK		AL109		Slightly.								90		14		19		114		13A					
Allison		3940/A206156		Slightly.																					
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE															
A761 8-8																									
NATURE OF ACCIDENT																									

DUTY ON WHICH ENGAGED:

LOCAL FLYING PRACTICE

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

INVESTIGATING OFFICER'S REPORT.

DATE: August 10th, 1942.

COMPOSITION:

P/O G.A. Styles (J10559) No. 14 Sqdn.

L. G. / W. M.

RECOMMENDATIONS:

1. That a periodic check every 90 hours be carried out on the hydraulic selector unit.
2. That all pilots be instructed to check the u/c being fully down and locked by selecting wheels down and checking with the hand hydraulic pump on the cross-wind leg just prior to turning into wind to land.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

CONCLUSIONS OF A.I.B. THIS ACCIDENT WAS DUE TO THE FAILURE OF THE STBD. LOCKING JACK TO OPERATE PROPERLY, EITHER BECAUSE OF DIRT IN THE SYSTEM OR BECAUSE THE PILOT DID NOT ALLOW SUFFICIENT TIME FOR WHEELS TO BECOME LOCKED. THE UNDERCARRIAGE WARNING HORN WAS UNSERVICEABLE AND HAD BEEN REPORTED. THE DEFINITE CIRCUMSTANCES OF THE FLIGHT ARE NOT KNOWN, BUT IT IS RECOMMENDED THAT UNLESS IT IS IMPERATIVE TO TAKE-OFF IMMEDIATELY MINOR DEFECTS OF THIS NATURE SHOULD BE ATTENDED TO BEFORE FLIGHT IS PERMITTED.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

AFTER MAKING A NORMAL LANDING THE AIRCRAFT TAXIED APPROXIMATELY 200 YARDS WHEN THE STBD WING BEGAN TO SINK AND CONTINUED TO DO SO UNTIL THE AIRCRAFT WAS SLIDING ALONG ON ITS PORT WHEEL RADIATOR COWLING AND WING TIP



PRIMARY CAUSE:

U/c failed to lock in the down position, probably due to normal accumulation of dirt in system.

J. Others

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

STBD oleo leg folded on landing.

35. U/c Defect

RECORDED BY

DATE

CHECKED BY

DATE