

YTUC	ON	WHICH	ENGAGED:

M.T. Driver was operating Electric

Flare Path Tender. NATURE OF ACCIDENT AND STAGE OF FLIGHT:

LAC Phaneuf walked down and relit number 3 flare which had gone out. then he moved away from the runway about 15 paces. Aircraft landed, swerved off the runway, and struck

and killed him instantly. A/C ground looped on landing.

leneous Gause

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

COMPOSITION:

SQUADRON LEADER H.M. WILSON CI 405 No. 2 S.F.T.S. UPLANDS. ONTARIO.

RECOMMENDATIONS:

IT IS SUGGESTED THAT NO LANDINGS OF TAKE OFFS BE PERMITTED WHILE ATTENDENT IS WORKING ON THE FLARE PATH OR IN THE VICINITY OF THE FLARE PATH.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

CONCLUSIONS OF A.I.B. :- THIS ACCIDENT WAS CAUSED BY AIRCRAFT 2757 GROUND LOOPING AND STRIKING LAC PHANEUF, WHO HAD BEEN ORDERED TO MAKE REPAIRS TO THE FLARE PATH. IS CONSIDERED THAT THE OFFICER IN CHARGE OF NIGHT FLYING SHOULD E WITHHELD LANDINGS AND TAKE-OFFS DURING THE TIME REPAIRS WERE THE INSTRUCTOR SHOULD HAVE TAKEN CORRECTIVE ACTION SOONER.

STATES THAT HE WAS AWARE HIS STUDENT HAD LEVELLED OFF TOO HIGH.

RECORDED BY DATE

CHECKED BY