

32 JU. 31 TECH. 30 DIJOB. 29 NEG'NCE 28 INEXP NCE 27 MISCEL. 26 INSTRUCT. 25 FLT. CONTR. 24 OTHERS 23 PRIMARY 22 FL. CONTS. 21 MOV. SURFS. 20 STAB. SURFS. 19 W. STRUTS 18 LAND GEAR 17 FLOATS 16 FUSE. OR HULL 15 TAIL SKID OR W. 14 ENGINE MOUNT. 13 MISCEL. 12 UNDTD 11 PRIMARY 10 FUEL SYS. 9 COOL SYS. 8 IGNIT. SYS. 7 LUB'N SYS. 6 ENG. STR. 5 AIRSCREW A. 4 ENG. CONTS. 3 MISCEL. 2 UNDTD 1 PRIMARY

19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

PILOT OTHERS AIRFRAME FAILURE ENGINE FAILURE

CAUSES OF ACCIDENTS

UNIT	9 S.F.T.S.	COM.		PLACE		DATE	3-11-42	TIME	1215
	Centralia, Ont.		# 1	Main Aerodrome		H.O. FILE	1109-72-69		

A/C TYPE	Anson II	No.	7256	CRASH CAT.	D 6
	Anson II		7269-D		D 4
	Anson II		7560		

NAME	RANK	No.	DUTY	RIES	SERIOUS
Dowden, M.E.	P/O	J12572	FI	Nil	FATAL INJURY
Drabble, C.	LAC	R148881	PP	Nil	

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS							
						INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.	
Anson II	7256	Slight											
Jacobs	3571	Nil											
Anson II	7269	Serious											
Jacobs	3089	Nil											
Anson II	7560	Slight											
Jacobs	3297	Nil											

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
A 28	4-11				

NATURE OF ACCIDENT

MISCELLANEOUS CAUSES
 HANDO.
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UNDTD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 FLIGHT
 FATAL
 INJ.
 CRASH

19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Practicing sequence nineteen.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

D.14.

While approaching the hangar parking area the Instructor allowed his a/c to taxi at an excessive speed. In an endeavour to slow up this the Instructor applied his brakes to find that there was insufficient control to prevent him from taxiing ~~PRIMARY CAUSE~~ into two parked aircraft in front of the hangars damaging all three craft.

COMPOSITION:

*M/SI
TCA/POT
MA/XA
H/SR*

RECOMMENDATIONS:

Further efforts are being put forward to endeavour to impress all aircrew with the importance of slow taxiing both with regard to accidents being avoided and also preventing tires from blowing.

Primary Cause.

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

~~Carelessness on the part of the Instructor.~~

Instructor placed on charge under Section 39A(1) (a) of the A.F.A.

9 COLLISIONS

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Anson II 7269 taxiing at an excessive speed collided with aircraft Anson 7256 and 7560.

RECORDED BY

DATE

CHECKED BY

DATE