	DOOR LE					FAILURE ENGINE				S. S			
11'	UNIT #2 S.F.T.S. COM.			USES OF ACCIDENTS PLACE M.A.				DATE 27.4.43 TIME 0950 H.Q. FILE 1100-29-95				.6. /	
A/C TYPE	Harvard II Harvard II	#3 10	No			CRASH CAT.	A A	SE X	ME	DAY X	NIGHT		(R)
	NAME		RANK	No.	DUTY		חוח			SER	IOUS	키 디곤 [/	.ల్/
L	Stuart, B. Lyons, C.		PO AC			Seriously Gritically					2	m z ×	XER /
E N O N											ARD AL No.		
PE OF										6		111/	AN/ -
	E A/F No.	EXTENT	REPC	RT SERIAL	DAT	E	нс	URS FLO		PILOTS	1	111/	0 /
1 📖	arvard II #299	OF DAMAGE		RM No.		IN	ST. NIGHT	ON T		TOTAL DUAL SOL	LAST O 6 MOS	.["]∃[/,	*6/ /
H.	asp 4755/962 arvard II #302	5 Total 2 Total										- G M &	
S 145	RSD <u>4986/Y18</u> NAL NO. & DATE	<u>\$8 Total</u>		COM	No. & [DATE	REPO	рт	FILE		DATE	S	

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY,	INVESTIGATING OFFICER	D.14)		
Sequences 6,7,8. Both aircraft.	OR COMMANDING OF			Ć		
NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/c approaching aerodrome for landir appeared to collide stalled and cras	SOMPOSITION:	CONCLUSIONS OF Cause of acciden part of the pers tower & the tend lookout & towarn to enable them t	nt was failure or sonnel in the cor er to keep a pro n the silots in a	ntrol) cper) amyle time		
DDIMADY CAUCT.	RECOMMENDATIONS: (2)	Flying control a in as much as si	at this station i	is negati <i>ve</i> sed to		
PRIMARY CAUSE: 26. Collision in the air 31. June 131		ask permission or give permission to land. Therefore it is considered that a greater degree of care & a higher of gree of skill is required on the part of flying control personnel than at (B) TECHNICAL (C) OTHER stations where positiontrol signals for landing & take of are used.				
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	1071/1 1071/17	/ x 2 7 x 2 7 REC	CORDED BY	DATE		
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41		CHE	ECKED BY	DATE)		
· · · · · · · · · · · · · · · · · · ·)))))))))		