

TECHNICAL OFFICER'S REPORT: PURPOSE OF FLIGHT: Engine and Airframe destroyed by impact with thees Dual Navigation Trip No. 13 and fire. NATURE OF ACCIDENT: Took off on a high level cross country COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: , flight, 2nd leg of which was under 2157 FINDINGS: SUMMARY No. hood. 16 m.W. of turning point from Obscure, but may have flown off track on 2nd ler) 2nd to 3rd leg, A/C was seen at very of X country, that its windows may have become low altitude in vertical or near verfrosted by flying into overcast while instrument tical bank, left wing low, slipping hood was still in use, that A/C may have assumed downward and making almost a complete an unusual position while in overcast from which turn to left before crashing into a safety pilot. i.e. instructor, owing to safety hood small area of bush, where it caught obscuring his view of part of instrument panel, was fire and burned. unable to recover before instrument hood could be removed and before A/C struck ground. RECOMMENDATIONS CLASSIFICATION: Due to possibility of exterior icing, various types 59. Obscure. of icing and their effect on A/C engine performance 23. not known, their avoidance and remedy be brought to attention of all pilots. CONCLUSIONS OF A.I.B. - Cause of accident obscure. ACTION TAKEN: 29 Fire-in crash 29 Note: No written record of authorization for presence of LAC MacKenzie in aircraft, in accordance CAP 100, Sec. 17, para. 18. R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 C. C. LTD, 7084-43 H. Q. 885.L 20