

PURPOSE OF FLIGHT: TE	CHNICAL OFFICER'S REPORT: JBF// PEC/ FCERT)
Seq. 18 (1-11))
NATURE OF ACCIDENT:	NIT
A/C crashed in low flying area. A/C took off at 0920 hours, and about _{F1} 1015 hours, it crashed in a right hand spin from about 3,000 altitude; after a large portion of its stbd wing had broken off in the air.	CAUSE: Undue stress placed on a/c in some unusual position causing a/c to lose large section of wing, spun vertically into ground fatally injuring both occupants on impact. RECOMMENDATIONS: This I.O. suggest that consideration be given to issuing a directive limiting the speed at which a high speed stall is demonstrated.) CONCLUSTONS OF AIB: Agree.
CLASSIFICATION: 28. Structural failure. 19. Part of Cofatcal SECONDARY OR CONTRIBUTORY FACTORS: 39. Structural Failure ACT R.C. X. F. L 20 (REVISED)	NOTE I F/O McIntyre was not medically examined following the accident on the alst March but he had spoke of the incident to the M.O. and during the conversation mentioned that a speed of 300 miles or there about had been attained in it. NOTE 2: One eye witness whose indentity could not be learned had stated to the Unit's C.E.O.at the scene of the accident that he had seen the a/c direction taken: out of a cloud, pull up suddenly, waver after which the wing broke off.
7M-4-43 (3202) K.P. 5051 H. Q. 885-L 20	C. C. LTD. 7084-43

())))))))