

61 () 60 () 59 () 58 () 57 () 56 () 55 () 54 () 53 () 52 () 51 () 50 () 49 () 48 () 47 () 46 () 45 () 44 () 43 () 42 () 41 () 40 () 39 () 38 () 37 () 36 () 35 () 34 () 33 () 32 () 31 ()

ACCIDENT CLASSIFICATION

UNIT 31 S.F.T.S. Kingston		COM. 3	PLACE M.A.		DATE 22-5-44	TIME 1645
A/C TYPE HARVARD II		NO. AJ647	CRASH CAT. "B"		H.Q. FILE 1300-AJ647	
PERSONNEL MACKENZIE, D.B.		RANK ALA	NUMBER SANF 330496	DUTY PP	INJURIES Uninj.	SIGNAL
						NO. C110
						DATE 22-5
						D 14 (REVISED)
						NO. 6
						CHECKED <input checked="" type="checkbox"/>
						#67

COMMAND
MONTH
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
INJURY
3RD
5
RAF
M

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ENGINE Wasp S3HI	ENGINE NUMBER (S) 9592/4722 Nil	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		21	17	41	54	61	85
							146

ACCIDENT CLASSIFICATION

1 () 2 () 3 () 4 () 5 () 6 () 7 () 8 () 9 () 10 () 11 () 12 () 13 () 14 () 15 () 16 () 17 () 18 () 19 () 20 () 21 () 22 () 23 () 24 () 25 () 26 () 27 () 28 () 29 () 30 () 31 ()

PURPOSE OF FLIGHT:

Advanced deflection Practice.

TECHNICAL OFFICER'S REPORT:

LUC/UDL ✓

NATURE OF ACCIDENT:

After completing an advanced deflection practice, pilot returned to aerodrome and joined the circuit on reaching the downward leg pilot endeavoured to let u/c down but found he was unable to move the selector lever. Tried all emergency methods of letting down the u/c, and when all these failed, came in and landed with wheels up.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY NO.

Investigation revealed that the locking pin on the axle end of the stbd oleo leg had ridden up on and jammed against the face of the upward locking latch. This could only have occurred as a result of the oleo leg sticking in the compressed position on take-off. The complete system worked perfectly after freeing. Presumable vibration in flight tended to free leg in its gland and the pressure caused the locking pin to bite into the locking plate and thus it resisted the pilot's efforts to select "Down".

CLASSIFICATION:

~~34. Wheels up landing.~~

17 Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

~~33. Technical defect.~~

34. u/c strain 34

ACTION TAKEN:

NIL