

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																			
CAUSES OF ACCIDENTS																																	
UNIT # 33 S.F.T.S.										COM.		PLACE										DATE 18-3-41		TIME 02:45									
Carberry, Man.										2		Aerodrome										H.O. FILE 1300-2804											
A/C TYPE Harvard.										No. 2804		CRASH CAT. C		SE X		ME		DAY		NIGHT X													
NAME										RANK		No.		DUTY		INJURIES						SERIOUS											
Trotter S.H.										F/O		40959		FI		Uninjured.						FATAL		INJURY									
Doig W.B.										LAC		1105936		PP		Uninjured.																	
																						CARD SERIAL No.											
TYPE A/F & ENGINE										No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS													
Harvard 2804										N11		D14		18-3-41		INST.		NIGHT		ON TYPE				TOTAL		LAST 6 MOS.							
Wasp S3H1 8465/4324										N11										DUAL SOLO				DUAL SOLO									
SIGNAL No. & DATE										UNIT No. & DATE				COM. No. & DATE				REPORT		FILE		DATE											
NATURE OF ACCIDENT																																	
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1															
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

UNDTD
 PRIMARY
 HAND.O.
 INSTS.
 WEATHER
 DRKMS.
 ALG SURF.
 OTHER
 UNDTD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 3RD.

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

L U / P S U / I

Night Flying Instructions.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: Commanding Officers Report.

COMPOSITION: 18-3-41

The pupil came in too low on his approach, and the instructor failed to check him in sufficient time to prevent him from striking the angle of glide indicator (positioned 100 yds. down wind from No. 1 Flare) with airscrew.

RECOMMENDATIONS:

In this particular instance the pupil should have been checked earlier for approaching too near the flares and undershooting. The instructor has realized this since, and the C.O. is of the opinion that he will not be involved in a similar accident in future.

PRIMARY CAUSE:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Instructor failed to check pupil in sufficient time to avoid striking the angle of glide indicator.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pupil carried out approach too low.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____