

M		
Taxiing preparatory to flight.	OR COMMANDING OFFICE	R'S REPORT:
ATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	Monthly Accident Return.
AJ 547 TAXIED INTO REAR OF AJ 552  nstructor was taxiing out from t	COMPOSITION:	7 1 10 / 2 T
armac to take off on No. 2 runwa		en e
e failed to see stationary a/c		
reparing to take-off, and came i	nto RECOMMENDATIONS:	
ollision with it, doing consider		
amage to the tail unit.		
RIMARY CAUSE:		
Failing to see stationary arcraf	't	
while taxiing.	•	
•		
	ACTION TAKEN:	
	(A) DISCIPLINARY (B)	TECHNICAL (C) OTHER
	Case admoni	shed.
		dorsed "Gross carelessness".
		41 APA AUTOTODE .
ECONDARY CAUSE OR CONTRIBUTING FACTORS:		
Colliding with stationary aircrs	ıft	
while taxiing to take-off.		RECORDED BY DATE