

DUTY ON WHICH ENGAGED: Instrument Flying	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Instructor applied brakes to avoid hitting steam roller on taxi strip and aircraft went up on nose damaging propellor tip.	Monthly Accident Return.
	COMPOSITION:
	RECOMMENDATIONS:
PRIMARY CAUSE: Lack of watchfulness on part of the pilot. Harsh use of brakes.	
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Log Book endorsed - "Taxiing - Carelessness."
ON THE STATE OF CONTRIBUTING FACTORS.	
Aircraft went up on nose damaging propellor tip.	RECORDED BY DATE
DLODGETTOL OTD*	