

TYPE OF A/C		CAUSES OF ACCIDENTS																MISCELLANEOUS															
		PILOT		OTHERS		AIRFRAME FAILURE												ENGINE FAILURE															
UNIT		COM.		PLACE		DATE		TIME		H.Q. FILE 1100 - 62 - 85 SE ME DAY NIGHT X X X																							
MONCTON, N.B.		No. 3		AERODROME		2-3-41		1100																									
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT		CARD SERIAL NO. FATAL INJURY																			
AVRO ANSON		6205		B				X		X		X																					
NAME		RANK		No.		DUTY		INJURIES		SERIOUS		CARD SERIAL NO. FATAL INJURY																					
HEBERT, J.C. (6285)		F/O		C469		F.I.		UNINJURED		FATAL INJURY																							
LADOUCEUR, C.J. (6205)		SGT		R52088		FI		UNINJURED		FATAL INJURY		CARD SERIAL NO. FATAL INJURY																					
PIKE, D.H. (6205)		LAC		R83593		PP		UNINJURED		FATAL INJURY																							
MCLAUGHLIN, P.A.		LAC		R82506				UNINJURED		FATAL INJURY		CARD SERIAL NO. FATAL INJURY																					
										FATAL INJURY																							
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																					
AVRO ANSON		6285		Slight								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.															
AVRO ANSON		6205		Nil				HEBERT -----		15 30		DUAL SOLO		DUAL SOLO		TOTAL		TOTAL															
CHEETAH (P) & (S)		Nil						LADOUCEUR-----		41 27		6 328		79 428																			
CHEETAH (P) & (S)		Nil																															
SIGNAL No & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE		NATURE OF ACCIDENT																					
A599		10-3-41																															

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

WINGS TEST

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

ANSON 6205 TAXIED INTO REAR ANSON 6285  
ANSON 6205, WHILE TAXIING TO TAKE-OFF POSITION

BEGAN TO APPLY BRAKES TO STEP BEHIND ANSON

6285 PARKED AHEAD. ON APPLICATION OF BRAKES THERE

WAS NO REACTION AND ANSON 6205 COASTED INTO  
ANSON 6285.

RECOMMENDATIONS:

PRIMARY CAUSE:

ANSON 6205 TAXIED INTO REAR ANSON 6285

STRUCTURAL FAILURE (BOWDEN CABLE BROKE)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL MODIFICATION OF BOWDEN CABLE BEING SUBMITTED.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

ANSON 6205 CONTRACTED EMPENAGE OF ANSON 6285.

BROKEN BRAKE CABLE ON 6205

RECORDED BY

DATE

CHECKED BY

DATE