

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER POC/PEDM OR COMMANDING OFFICER'S REPORT: Night flying sequences 7 & 8 Court of Inquiry. NATURE OF ACCIDENT AND STAGE OF FLIGHT: September 18th, 1941. DATE: Aircraft took off and after climb-COMPOSITION: ing to approximately 500 ft. was President S/L Hodson, K.L.B. observed to turn left and lose Member F/o Kimball. G.F. height until it disappeared from Member F/o Morris, H.K. RECOMMENDATIONS view. 1. More emphasis should be placed on cockpit drill. 2. The procedure of Command Instruction T.150/3, PRIMARY CAUSE: para. 4 (b), be strictly adhered to, with the L.A.C. Moore did not carry out a exception that a gentle climbing turn be executed thorough cockpit check in that the above 500 feet if the direction of take-off would elevator trimming tabs were left carry the aircraft over the water. in the landing position. ACTION TAKEN: Nil It is felt that if there has been an occupant in weights had not come through the seat if the is, therefore, recommended that these counter balance weights be more firmly anchored. SECONDARY CAUSE OR CONTRIBUTING FACTORS: The aircraft went out of control, stalled at low altitude, and dove into the ground, following a rapid RECORDED BY DATE climb on take-off due to the elevator tabs being set in the tail heavy position. CHECKED BY DATE