

DUTY ON WHICH ENGAGED:	
······································	COURT OF INQUIRY, INVESTIGATING OFFICER
, <u> </u>	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Monthly Accident Return.
Engine was being run up during the	COMPOSITION: 27 - / Y. T. Y.
course of daily inspection by the	
maintenance squadron and chocks sumk into soft ground causing a/c	- Paris
to jump the chocks. The a/c swung to	
the left and the port wing of 3142	RECOMMENDATIONS:
was completely sheared off by 3140	
MINIMAX airscrew. The starboard	
wing of 3140 was slightly demaged by	
the port wing of 3142. Airscrew of	
3140 to be replaced.	
	ACTION TAKEN:
Running up of engine by inexperienced	
aircraftsman who was not authorized t	
perform such duty.	Cpl. Cameron R.RAdmonished.
	Flt. Sgt. Firth L.FReprimand.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	Sgt. Nelson K.NAdmonished.
Ф.	RECORDED BY
The port wing of 3142 came into conta	RECORDED BY DATE .
The port wing of 3142 came into conta with airscrew of 3140.	RECORDED BY DATE CHECKED BY DATE