

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
NIGHT FLYING PRACTICE.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Monthly Accident Return.
Aircraft Landed with undercarriage retracted. Approaching to land at night a/c	COMPOSITION: // /UDW
warning light showed green and horn	
did not blow when throttles closed	
resulting in belly landing damaging	
both propellors and cowling. Manue	
operation of u/c caused u/c limit	switch
ANNALY CAUSE to jam, showing green	
and not allowing horns	s to blow.
PRIMARY CAUSE.	0 00 01011
Pilot failed to ensure that	
wheels were down causing belly	ACTION TAKEN:
landing.	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
randing.	All aircraft are to be declared un-
	serviceable after U-C operated manually
	and the down limit switch to be examined.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
U/C warning devices functioning	
	RECORDED BY DATE
U/C warning devices functioning	RECORDED BY DATE
U/C warning devices functioning	RECORDED BY DATE CHECKED BY DATE