

	•		
1))))))))))))))	
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
)	Solo flying.	OR COMMANDING OFFICER'S REPORT:	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Monthly Accident Return.	
)))	Starboard engine nacelle crumbled, engine cowling distorted, both undercarriages sheared off. Pilot ground looped.	1 52/235/22 C	
)		RECOMMENDATIONS:	
)			_
)	PRIMARY CAUSE:		1
)	Landing slightly crosswind sudden change in wind direction caused ground loop. Starboard engine cut out on approach, initiating swing.	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other Pupils warned about low idling speeds on engines and results of same.	
)))	SECONDARY CAUSE OR CONTRIBUTING FACTORS: Oleo legs collapsed under strain.	RECORDED BY DATE	1 1

CHECKED BT DATE

CHECKED BY