

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: INVESTIGATING OFFICER'S REPORT Dual instrument flight. NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: October 17th, 1941. On recovery from spin engine took fire - pupil abandoned aircraft on S/L Creighton. G.E. order of pilot who subsequently got fire under control and landed wheels RECOMMENDATIONS: up. That Pilots be taught more thoroughly to re carburettor icing symptoms and the proper corrective and that they should be further informed of the PRIMARY CAUSE Throttle stuck fully closed and danger of throttle pumping. engine causht on fire. ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other Investigation revealed "Carburettor Icing" as contributing factor. Instructors and pupils warned against this hazard. 0371 SECONDARY CAUSE OR CONTRIBUTING FACTORS: Pilot made forced landing in rough field wheels up. RECORDED BY DATE DATE CHECKED BY