

DUTY ON WHICH ENGAGED: Both aircraft solo circuits. MATURE OF ACCIDENT AND STAGE OF FLIGHT: 7833 landed on top of 7663 about 25 feet in the air as both aircraft were levelling out for a landing on east end of east- west runway. PRIMARY CAUSE: Pilot of aircraft 7633 failed to observe aircraft 7663 underneath him as bothwere approaching and pilot of 7833 made a normal approach. Investigations being carried out under arrangements. ACCION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER RECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft collided just after landing. AIRCRAFT 7833 COLLIDED WITH 7665.	j	· · · · · · · · · · · · · · · · · · ·)))))))	$\rightarrow \rightarrow \rightarrow \rightarrow$
7833 landed on top of 7663 about 25 feet in the air as both air- craft were levelling out for a landing on east end of east- west runway. PRIMARY CAUSE: Pilot of aircraft 7833 failed to observe aircraft 7663 underneath him as bothwere approaching and pilot of 7833 made a normal ap- proach. Investigations being carried out under arrangements. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft collided just after landing. AIRCRAFT 7835 COLLIDED MITH 7663.))			CER)
landing on east end of east- west runway. PRIMARY CAUSE: Pilot of aircraft 7833 failed to observe aircraft 7663 underneath him as bothwere approaching and pilot of 7833 made a normal approach. Investigations being carried out under arrangements. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft collided just after landing. AIRCRAFT 7833 COLLIDED WITH 7663.)	7833 landed on top of 7663 about)
Pilot of aircraft 7833 failed to observe aircraft 7663 underneath him as bothwere approaching and pilot of 7833 made a normal approach. Investigations being carried out under arrangements. Secondary cause or contributing factors: Aircraft collided just after landing. Recorded by Date Aircraft 7833 collided with 7663. Checked by Date)	craft were levelling out for a landing on east end of east-west runway.		PX 74)
Aircraft collided just after landing. AIRCRAFT 7833 COLLIDED WITH 7663. CHECKED BY DATE		Pilot of aircraft 7833 failed to observe aircraft 7663 underneath him as bothwere approaching and pilot of 7833 made a normal approach. Investigations being	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	1ER 	
))))	Aircraft collided just after landing.		_	
	ラ ト			CHECKED BY	DATE)