

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	
Sequence 6/7/8/10/13/15/16/22. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	
Pilot states wheels would not retrace after take off and port wheels would not lock for landing although proper procedure carried out. Port undercarriage folded during landing run	d r	
damaging undercarriage rampiston rod. PRIMARY CAUSE:	Nil	
Only possible cause other than in- correct use of controls is de- freezing of water which was found in the hydraulic fluid drained from the uncercarriage ram cyl- inder.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	Nil	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
Port undercarriage folded during landing run.	RECORDED BY DATE	
)	CHECKED BY DATE	—
)