

DUTY ON WHICH ENGAGED:

Solo practice.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

RL70

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Aircraft taking off - air craft swung left 90 degrees bending undercarriage mounting and star-board engine mount. (Ground looped)

05/PSS/VSS

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Student failed to correct swing

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Further instruction proper procedure to correct swing.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft ground looped bending undercarriage mounting.

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____