

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Dual instruction.

OR COMMANDING OFFICER'S REPORT:

RL70

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Tiger Moth 4946 piloted by R96157
LAC Krupp E.C. taxied into air-
craft 5002 striking upper starboard
wing tip. Aircraft 4946 undamaged.

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Aircraft 4946 taxied on wrong side
of taxi strip. Failure of pilot
of A/C 4946 to see A/C 5002.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Student severely reprimanded for carelessness.
Log books endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

A/C taxied into A/C 5002.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____