

TYPE OF A/C	PILOT																		OTHERS										AIRFRAME FAILURE																						ENGINE FAILURE																																
	CAUSES OF ACCIDENTS																																																																																		
	UNIT	Central Flying School, Trenton																		COM.	1																		PLACE	1/2 Mile West of RCAF, Verdram, Trenton, Ont.																						DATE	1-22-17						TIME	1025													
	A/C TYPE	Twin																		No.	215 B						218						CRASH CAT.	C 2						SE X	ME		DAY X	NIGHT				H.Q. FILE	1100-2-17																																		
CATEGORY	TYPE OF ENGINE	NAME																		RANK	No.						DUTY						INJURIES												SERIOUS																																						
		Widderton, B.E. 215 (D)																		A/C	57320						I.						Uninjunct.												FATAL	INJURY																																					
		Kirley, G.A. 218																		Sgt	233811						P.F.						Uninjunct.												CARD SERIAL No.																																						
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE		REPORT FORM	SERIAL No.	DATE		HOURS FLOWN BY PILOTS																																																																										
									INST.		NIGHT		ON TYPE				TOTAL		LAST 6 MOS.																																																																
Civet		573	Slight						2		16		36 38		100 103																																																																				
Civet		545	Slight						1		16		40 51		96 120																																																																				
SIGNAL No. & DATE			UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE																																																																
10-10-17																																																																																			
NATURE OF ACCIDENT																																																																																			

MISCELLANEOUS CAUSES  
 HAND O.  
 INSTS.  
 WEATHER  
 ERASERS  
 2ND CAUSE  
 OTHER  
 UND/TD  
 PRIMARY  
 TAXIING  
 LANDING  
 TAKE OFF  
 FLIGHT  
 STATRY  
 FATAL  
 INJ.  
 3RD.

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Instructional solo flight.

OR COMMANDING OFFICER'S REPORT:

Investigating Officer's Report.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: 16.12.41.

Airscrew of 215 struck undercarriage of 218 in flight.

COMPOSITION:

F/LT.

D.G. CHOWN.

C.1614.

RECOMMENDATIONS:

Disciplinary action against the pilots concerned.

P/O Middleton, B.E. and Sgt. Kirley, S.A.

PRIMARY CAUSE:

(a) Carelessness on the part of No.

J7820 P/O Middleton, B.E. (Pilot of Fleet Fawn No. 215), in that he failed to keep a careful check on the position of Fleet Fawn No. 218, which he had noticed taking off at the same time as himself.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(B) Carelessness, to a lesser degree than the above, on the part of No. R88811 Sergeant Kirley, S.A. in that he failed to keep a careful check on the position of Fleet Fawn No. 215, which he knew had taken off

Endorsation of Instructors and Pilots log book in accordance with C.A.P.100

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

in close proximity to himself.

Airscrew and upper mainplane of Fleet 215 struck undercarriage of Fleet 218 in Flight.

RECORDED BY

DATE

CHECKED BY

DATE