

duty on which engaged: Advanced radio navigation.	OR COMMANDING OFFICER'S REPORT: 31 20/PCSE/E7/17/PCSE
NATURE OF ACCIDENT AND STAGE OF FLIGHT: On entering down wind leg of circuit	<u>DATE:</u>
A/C ran out of gasoline before pilot could restart engine by changing tanks A/C struck top of trees-engine restarted and safe landing made on runway.	RECOMMENDATIONS:
	Nil
Caused faulty cockpit drill due to carelessness and resulting in engine failure. Pilot placed on charge.	ACTION TAKEN:
(2)	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Log Book endorsed "Carelessness". Pilot awarded 7 days C.P. plus 6 days pack drill.	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
A/C struck trees folding loading edges of both wings.	RECORDED BY DATE
R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41	CHECKED BY DATE
· · · · · · · · · · · · · · · · · · ·	