

DUTY ON WHICH ENGAGED: Sequences 6 7 8.	COURT OF INQUIRY, INVESTIGATION OR COMMANDING OFFICER'S REPO	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: On landing A/C began to swing to left, full opposite rudder and brake applied but ground looped.	DATE: COMPOSITION:	R.170
	RECOMMENDATIONS:	
PRIMARY CAUSE: Crosswind and pilots error in judgment.  2. Jewery	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL  Student Flight Tested	(C) OTHER - Inexperienced on type.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:  Pross wind on runway caused A, C to cound loop.		RECORDED BY DATE