

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER CONTROL / FOR 19 2/1 Night solo circuits and landings. OR COMMANDING OFFICER'S REPORT: Court of Inquiry NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 15-4-42 I.AC. Yates had received an instrumentomposition: take-off prior to reporting for Pres. S.L. K.A. Gordon (C783) R.C.A.F.Sta.Rockelif night flying duties. He was authorized F.O. H.J. Russell (C9370)No.2 SFTS., Uplands. by his instructor to carry out two 1 hr. F.O. S.Berger (C9594) RCAF. Sta.Rockcliff() solo periods on circuits and landing COMMENDATIONS: He had completed half of this and, at WHILE LEADING LIGHTS WERE USED, IT IS POINTED OUT BY THE COURT THAT NO PARACHUTE FLARES ARE CARRIED BY AIRCRAFT ON NIGHT CIRCUITS the time of the crash was carrying out AND LANDINGS AT THIS STATION. IT IS SUGGESTED THAT HAD FLARES PRIMARY CAUSE: his second hour. BEEN CARRIED AND HAD THE PILOT RELEASED ONE IMMEDIATELY HE Aircraft struck the ground from a EXPERIENCED TROUBLE, THE LIGHT FROM THE FLARE WOULD HAVE GIVEN HIM AN INDICATION OF HIS ALTITUDE AND HE MIGHT HAVE REGAINED CONTRO spiral dive resulting from an error OF THE AIRCRAFT IN TIME TO AVOID THE ACCIDENT. of judgment on the part of the pilot. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL CONCLUSION OF A.I.B. AIRCRAFT, SHORTLY AFTER TAKE OFF, WENT INTO A RIGHT HAND SPIRAL DIVE AND CRASHED. THE PUPIL PILOT, WHO HAD JUST COMPLETED ON HOUR'S NIGHT FLYING, TOOK OFF IN A LIGHT RAIN AND WAS UNABLE TO RECOVER CONTROL WHEN NO WENT INTO A SPIRAL DIVE TO THE RIGHT. THE TURN TO THE RIGHT WAS SECONDARY CAUSE OR CONTRIBUTING FACTORS: CAUSED BY RUDDER TRIM - APPARENTLY THE ERROR OF THE PUPIL. Aircraft arashed. WERE CERTAIN ASPECTS OF THE TRAINING OF THIS PUPIL THAT HERE RECORDED BY NOT ACCORDING TO TRAINING INSTRUCTIONS BUT ARE CONSIDERED NOT TO HAVE A BEARING ON THIS ACCIDENT. THE A.O.C. HOWEVER STATED THAT HE WAS TAKING THE MATTER UP WITH THE UNIT