

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																			
CAUSES OF ACCIDENTS																																	
UNIT <b>12 S.F.T.S.</b>										COM. <b>2</b>		PLACE <b>M.A.</b>										DATE <b>22-4-42</b>		TIME <b>0520</b>									
A/C TYPE <b>Crane</b>										No. <b>8198</b>		CRASH CAT. <b>C.10</b>		SE	MEX <b>X</b>	DAY		NIGHT <b>X</b>															
NAME										RANK		NO.		DUTY		INJURIES				SERIOUS													
<b>Martin R.J.</b> <b>Kerns T.D.</b> <b>Willison R.P.</b>										<b>LAC. GB1387761</b> <b>P/O J8969</b> <b>SGT. R61661</b>		<b>P.P.</b> <b>I.</b> <b>I.</b>		<b>Uninjured.</b> <b>"</b> <b>"</b>				<b>FATAL</b> <b>INJURY</b>															
																		CARD SERIAL No.															
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM	SERIAL No.	DATE		HOURS FLOWN BY PILOTS																							
Crane		8198		Slight						INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS																	
Crane		7729		Slight						23	10	36	19	77	77																		
Jacobs		P21257/S21184		Slight - Nil						31	15	5	Nil	34	30																		
Jacobs		P21139/S22080		Nil - Nil																													
SIGNAL No & DATE				UNIT No & DATE				COM No. & DATE				REPORT				FILE		DATE															
CT-48				22-4-42																													
NATURE OF ACCIDENT																																	

CAUSES  
 STAGE OF FLIGHT  
 MISCELLANEOUS  
 HAND O.  
 INSTS.  
 WEATHER  
 DRKNS.  
 ALG SURF.  
 OTHER  
 UN'D TD  
 PRIMARY  
 TAXING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STAFFRY  
 FATAL  
 INJ.  
 3RD.

DUTY ON WHICH ENGAGED:  
Taxiing A/C at night.

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:  
Crane 7729 was parked on tarmac  
without lights and crane 8198 collided  
with it.

DATE:  
COMPOSITION:

*JCH/11/57*  
*7/24/57*

RECOMMENDATIONS:

**N11**

PRIMARY CAUSE:

Inability of pilot in A/C 8198 to  
see parked A/C 7729, due to aircraft  
7729 parked on tarmac without lights.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Disciplinary action to be taken against crew  
of 7729.**

*Collision*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft 8198 collided with aircraft  
7729.

RECORDED BY

DATE

CHECKED BY

DATE