

DUTY ON WHICH ENGINEES	COURT OF INQUIRY, INVESTIGATING OFFICER
Authorized transportation flight	OR COMMANDING OFFICER'S REPORT:
to Dartmouth, N.S. for the purpose of exchanging airpraft.	Court of Inquiry
WHEN A C WAS A FEW FEET OFF THE GROUND, ONE OR BOTH ENGINES SPUTTERED MOMENTARILY. A C	DATE: 8-6-42 COMPOSITION:
SANK TO THE GROUND, ENGINES PICKED UP AND A/C CLEARED THE RUNWAY TO CONTINUE IN A STRAIGHT CLIMB. AT 50 FT A LEFT BANK WAS ASSUMED WHICH GREW STEEPER DEVELOPING A	PRES. W.COMDR T.C. DICKENS NO.L6243 EASTERN AIR COMMAND MEM . S/LDR S. VOLK R.C.A.F. TOR BAY. F/LT. D.A. GILLIS NO. 5 C.A.S. SQD. TOR BAY. RECOMMENDATIONS:
SIDESLIP. A/C COMMENCED TO SINK, THROTTLES APPEARED CLOSED. A/C STRUCK THE GROUND	(1) THAT DEFINITE INSTRUCTIONS BE ISSUED AS TO THE NUMBER OF
BURST INTO FLAMES AND WAS TOTALLY DAMAGED. PRIMARY CAUSE:	PERSONS THAT MAY BE CARRIED AS PASSENGERS IN EACH TYPE OF OPERATIONAL AIRCRAFT.
(1) HUMAN FAILURE ON THE PART OF THE RILGT. (11) HUMAN ERROR ON THE PART OF THE PILOT.	(11) THAT WEIGHT SHEET SUMMARIES ARE PREPARED BEFORE FLIGHT BY ALL
(111) STRUCTURAL FAILURE OF THE AIRFRAME.	PILOTS OF HEAVY TWIN ENGINED OPERATIONAL AIRCRAFT."
(IV) FUEL STARVATION.	ACTION TAKEN:
FGR FURTHER INFORMATION SEE FILE 1700 - 761	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
DUT OF CONTROL	CONCLUSIONS OF A. I.B.
(14)	THIS ACCIDENT WAS FULLY INVESTIGATED BY SQUADRON LEADER POLLAR AND FLYING OFFICER CARON OF THIS BRANCH.
SECONDARY CAUSE OF CONTRIBUTION	WHILE THE CAUSE OF THE ACCIDENT REMAINS OBSCURE, THE FOLLOWING MUST BE REGARDED AS CONTRIBUTORY CAUSES;-
SECONDARY CAUSE OR CONTRIBUTING FACTORS: ATREMATE CRASHED AND BURNEDS	(1) THE LCAD WAS INCORPORT A PROPERTY OF
FIRE - IN CRASH.	(IV) MISUSE OF CONTROLS BY DISCRECORDED BY DATE
$(^{29})$	Examination of documents concerning this aircraft revealed that there had been no N.C.C. percentage check on this aircraft between 23/3/42 and 6/5/42, ie., enree the aircraft left Darthou