

Forced landing approaches. OR COMMANDING OFFICER'S REPORT: K170 NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pupil opened throttle to climb away, the engine failed to respond and pupil thinking he would finish landing run in windward boundary retracted the u/c and a/c subsided on ground with wheels up. Aircraft sustained damage to flaps and OFM/R/AOP/PCDE/ COMPOSITION: RECOMMENDATIONS: Nil
retracted the u/c and a/c subsided RECOMMENDATIONS: on ground with wheels up. Aircraft sustained damage to flaps and
retracted the u/c and a/c subsided RECOMMENDATIONS: on ground with wheels up. Aircraft sustained damage to flaps and
retracted the u/c and a/c subsided RECOMMENDATIONS: on ground with wheels up. Aircraft sustained damage to flaps and
Aircraft sustained damage to flaps and Nil
PRIMARY CAUSE: airscrew.
Failure of engine to respond to throttle opening.
ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Pupil interviewed by C.F.I. Log Book endorsed "Carelessness."
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft landed with u/o retracted. 26. ENGINE TROUBLE-
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41 ACCIDENT CHECKED BY DATE