

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Routine flight. COURT OF INQUIRY NATURE OF ACCIDENT AND STAGE OF FLIGHT: September 23rd, 1942. DATE: Port engine sputtered and cut out COMPOSITION: at 20 feet three quarters down the S/L R.A. Ashman No. 115 BR. Sqdn. runway. Pilot increased boost on F/L F.B. Curry No. 115 BR. Sadn. starboard engine but began to lose P/O L.H.J. Shebeski No. 115 BR. Sadn. power and height. Jettisoned bombs RECOMMENDATIONS: and mushed into trees and burst into flames. PRIMARY CAUSE: Failure of port engine possibly du to faulty setting of Hot air shutters and faulty fitting of Amal valve balance. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Failure of starboard engine due to Nil. fusing of plugs under 9 pounds Conclusions of A.I.B. boost pressure Agree with the Findings and the remarks of the A.C.C. SECONDARY CAUSE OR CONTRIBUTING FACTORS: direcraft crashed into trees and RECORDED BY burst into flames DATE CHECKED BY