

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

CAUSES

STAGE OF FLIGHT

PILOT

OTHERS

AIRFRAME FAILURE

ENGINE FAILURE

CAUSES OF ACCIDENTS

UNIT

3 F.I.S.

COM.

PLACE

DATE 29-9-42

TIME 1030

Arnprior, Ontario

3

Main Aerodrome

H.Q. FILE

1100-43-51

A/C
TYPE

No.

CRASH
CAT.

SE

ME

DAY

NIGHT

Fleet Finch

4351

C 1

x

x

NAME

RANK

No.

DUTY

INJURIES

SERIOUS

Jeffery, R.H.C.

E/L

C1475

FI

Uninjured.

Staples, J.F.

SGT

10191742 PP

Uninjured.

FATAL

INJURY

CARD
SERIAL No.TYPE A/F
& ENGINE

No.

EXTENT
OF DAMAGEREPORT
FORMSERIAL
No.

DATE

HOURS FLOWN BY PILOTS

INST.

NIGHT

ON TYPE

TOTAL

LAST
6 MOS.

Finch

4351

Slightly

Kinmer 1731/6384

Nil.

SIGNAL No. & DATE

UNIT No. & DATE

COM. No. & DATE

REPORT

FILE

DATE

A 4

29-9

NATURE OF ACCIDENT

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Flying training.

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

When taxiing wing tip struck
obstruction edge of incomplete
runway.

RECOMMENDATIONS:

PRIMARY CAUSE:

Carelessness on part of pilot
in not keeping a proper lookout.

Collisions

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C struck stone truck carrier.~~

RECORDED BY

DATE

CHECKED BY

DATE