

SCHEDULE FLIGHT.  NATURE OF ACCIDENT AND STAGE OF FLIGHT:  AIRCRAFT ON LEAVING POSITION ON LINE SWUNG TO THE STARBOARD PORT WING COMING IN CON- TACT WITH BUILDING CAUSING AIRCRAFT TO SWING TO THE PORT PROPELLOR AND FRONT OF AIRCRAFT COMING IN CONTACT WITH BUILDING.	COURT OF INQUIRY. INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:  DATE: COMPOSITION:  RECOMMENDATIONS: Recommend that the camera obscura building and fitting.
FRIMARY CAUSE: Lack of judgment in texiling.	be removed immediately as they are now obsolete and useless since this School has ceased bombing. The building and fittings constitute a hazard to taxiing as they are in the parking area.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Pilot placed under arrest and summary of evidence now being taken.
secondary cause or contributing factors:  A/6-struck building.	RECORDED BY DATE