



DUTY ON WHICH ENGAGED:

Ferrying aircraft from Noorduyun Limited to No. 6 Repair Depot.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Collided with stationary automobile while taxiing on runway under construction.

PRIMARY CAUSE:

~~Carelessness on part of pilot, although vision obscure.~~

9. COLLISIONS.

~~Nil~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "gross carelessness".

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

DATE:

COMPOSITION:

INVESTIGATING OFFICER

F/L G.R. Lortie C.4618

RECOMMENDATIONS:

TCO/PCT/XOU ✓

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Runway construction and lack of a control tower. A/C struck a stationary A/C.~~

RECORDED BY

DATE

CHECKED BY

DATE