

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Ferrying from St. Hubert to Uplands.

OR COMMANDING OFFICER'S REPORT:

✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Engine failed on take-off. A/C
forced landed just outside of
aerodrome.

COMPOSITION:

D-14
OEM/AOP/ES/NR/NR/O.

RECOMMENDATIONS:

PRIMARY CAUSE:

Engine failure, possibly
due to carburettor icing.

15. FORCED LAND.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

A/C force landed.

26. ENGINE TROUBLE - 21
ACCIDENT.

RECORDED BY

DATE

CHECKED BY

DATE