

Dual instructional flight. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Stalled after take off and spun in. Engine failure after take-off, due to petrol cock being turned off. A/c stalled & spun into ground.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: DATE: 10 Dec./42 COMPOSITION: S.L. R.D. Adams (19127), #37 S.F.T.S. OOC/AOC/AO)
PRIMARY CAUSE: A STALL RESULTING IN A SPIN AT A HEIGHT TOO LOW FOR RECOVERY. 14. Out. OF CONTROL.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER CONCLUSIONS OF A. I. B. A STALL RESULTING IN A SPIN AT A HEIGHT TOO LOW FOR RECOVERY.)
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Misuse of controls. 26 ENGINE TROVELLE ACCIOENT R.C.A.F. FIRMLIO REQ. 1247 10M—15-11-41	RECORDED BY DATE CHECKED BY DATE)))))))))))))))))))	