

		((
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Local flying practice.	OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 28.12.42 COURT OF INQUIRY INVESTIGATION OFFICER	
Aircraft apparently came in contact with high tension wire tearing off rudder.	COMPOSITION: S/L. Maw, D.M. (AFC) #31 B. 8	6 G. S.
PRIMARY CAUSE: STRIKING HIGH TENSION CABLES WHILE LOW PLYING BELOW MINIMUM OF 250 ST., LAID DOWN IN C.A.P. (SECTION: 14, PARA. 1, WHICH STATES HOW THIS SEQUENCE IS TO BE PRACTISED. 22. 22. COLLISIONS ORSTR. SECONDARY CAUSE OR CONTRIBUTING FACTORS:	RECOMMENDATIONS: Move the Low Flying Area to a place where the terrain and obstructions are more suitable for this practice. High tension cables should not run closer than 5 or 10 miles from boundary. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER CONCLUSIONS OF A.1.B. SEE SUMMARY OF ACCIDENT INVESTIGATION No. 740.	
	RECORDED BY	DATE
C.C.A.F. FORM L20 REQ. 1247 10M15-11-41	CHECKED BY	DATE