

))))))))))))))))))))))))))))))))))))))
)	bolo practice.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:)
))	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Aircraft hit high broken colors above by eye witnesses to fly low along a river bed. After hitting wires A/C	F/L Livermore, R.R. (C896) 15 S.F.T.S. Claresholm.)
)	crashed into left bank. A/C burnt out after impact.	/LCO/PoL/CN Alta. RECOMMENDATIONS:)
)	PRIMARY CAUSE: Unauthorized low flying.	Severe and drastic punishment in all cases of disobedience of Flying Orders - particularly that personnel involved in serious accidents should be cashiered or discharged as appropriate.))
) V))	22. COLLISIONS. OBSTR.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER CONCLUSIONS OF A.I.B. Furil pilot, while deliberately engaging in unauthorized low flying, allowed his A/C to strike high tension power lines, causing it to crash to the ground where it caught fire and was totally destroyed.)
) A,))	A/C crashed on river bank. 42. UNAUTH. LOW Figing (42) 8.C.M.F. FORM LED BOOK 1017 10M-15.11.41	RECORDED BY DATE) CHECKED BY DATE))
))		ļ