/	31 30 29 28 27 26 25 24 23 25 24 23 25 24 23 25 24 23	////	18 17 16 17 16 18 17 16 18 17 16 18 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18	15 14 13 12 00 4 01 11 13 12		3 7 6 5	4 3 2 M.5.
PE OF A/C	PILOT OTHERS OUNIT 149 Squadron COM.	CAUSES O	FAILUR	IDENTS	ENGINE DATE 2-12-42	FAILURE	1 +200
\f^	A/C TYPE Besufort 1 N A M E	NO. NIOO5 RANK NO.	CRAS CAT.		SE ME	DAY NIGHT X SERIOUS	M Harrier
NGINE	Wilson, J.T. Luty, J. Tucker, C.N.	S/L C244 SGT 5502 AC1 1385418	OC S	Slight Slight Serious		1 3	M Z THER
PE OF ENC		SGT R51774	OC F	Glled.		SERIAL NO.	PRINTS (TIME)
1 }	TYPE A/F No. EXTENO OF DAMA	GE FORM No.	DATE	INST. NIGHT	ON TYPE T	OTAL LAST	TATONO LANDING LANDING LANDING TO THE COLUMN
GORY	Beaufort N1005 Total Taurus XII A153004/A153	i I			DAL SOLO BUA	3010	I G CT CAL
CATEC	SIGNAL NO & DATE UNIT NO.	& DATE COM	, No. & DATE	REPORT	FILE	DATE	STATELY THE STATE OF THE STATE
<u>'</u>	2 E V S 9 L 8 6 01 S	/ 7 7 7 7	91 LI	81 61 05 15	2 82 82 82 S	2 92 LZ 82	62 OE IE

DUTY ON WHICH ENGAGED:

Flight test.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C crashed on take-off.

SGT. LUTY (AFM) IN CO-PILOT SEAT, THROUGH
MISUNDERSTANDING RETRACTED U/C BEFORE A/C
BECAME AIRBORNE CAUSING A/C TO STAGGER INTO
AIR OFF END OF RUNWAY TO A HEIGHT OF 20 FEET.

A/C LOST HEIGHT, RIGHT WING DROPPED, HIT
GROUND, A/C CAUGHT FIRE AND CRASHED.
PRIMARY CAUSE:

Negligence on part of pilot in attempting to fly as first pilot en Beaufort A/C before being prop-

en Beaufort A/C before being properly checked out by qualified.

Resufort pilot.

14. OUT. OF CONTROL

secondary cause or contributing factors: U/C retracted before becoming airborne causing A/C to stagger into air and crash.

30 FIRE - ON GROUND.

R.C.A.F. FORM 120 REG. 1247 10M-15-11-41

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

DATE: 2-12-42 OU PC DUW/C/PCM/UC DO/ COMPOSITION:

G/C Trecarten C.L. (Clo3) Nestern Air Command.

F/L Trigance, K.W. (40576) 32 O.T. S. Patricia $B_{\rm a}$ y. F/C Williams T.C. (J11268) 122 Sqdn. Patricia Bay.

RECOMMENDATIONS:
THAT THE PROVISIONS OF C.A.P. 100, SEC. 8, ALL PARAGRAPHS, BE RIGIDLY ENFORCED. THAT THE PROVISIONS OF C.A.P. 100 SEC. 6, BE AMENDED TO INCLUDE A PARAGRAPH FORBIDING OCCUPANTS OF AN A/C OPERATING CONTROLS OTHER THAN THOSE REQUIRED BY THEIR NORMAL DUTIES. THIS MIGHT BE QUALIFIED BY A STATEMENT THAT IN A CASE OF EMERGENCY, THE PILOT MAY ORDER ANY MEMBER OF THE CREW TO OPERATE OR ASSIST IN OPERATING CERTAIN CONTROLS PROVIDED

THAT HE (THE PILOT) IS SATISFIED THAT SUCH ACTION IS NECESSARY FOR THE SAFE OPERATION OF HIS AIRCRAFT, OR NECESSARY TO MINIMIZE A PRESENT DANGER. IT SHOULD BE POINTED OUT THAT SUCH AN ORDER MUST BE DEFINITELY UNDER-STOOD AND ACKNOWLEDGED BY THE OCCUPANT EXECUTING IT.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER PILOT PLACED ON CHARGE UNDER SECTION 39A OF THE AIR FORCE ACT.
CONCLUSIONS OF A. I. B.

POOR AIRMANSHIP. THE PILOT, COMMANDING OFFICER OF THE SQUADRON, ATTEMPTED TO TAKE-OFF IN BEAUFORT AC, STAGGERED INTO THE AIR, STALLED AND CRASHED, ACC CATCHING FIRE. THE PILOT WAS INEXPERIENCED ON TYPE AND WAS NOT PROPERLY CHECKED OUT BY QUALIFIED BEAUFORT PILOT.

RECORDED BY DATE

CHECKED BY

DATE