

## CASPIR Aircraft Accident Cards

---

**Serial:** FP754

**Title:** Avro Anson Mk. II serial:FP754 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 2 aircraft on 1943-January-18. They are: Anson II s/n FP998, Anson II s/n FP754. This accident involved 4 people. Rome RM, Sanders HG, Wilmotdear ATC, Worley RS

**Keywords:** RAFAnson II,FP754,33 SFTS,33 Service Flying Training School,Aerodrome,1943-January-18,Rome,Sanders,Wilmotdear,WorleyRCAF L20

**Created:** 1943-01-18

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP754>



DUTY ON WHICH ENGAGED:

Local solo formation flying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

*MULTI*

D.14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil pilots carrying out formation exercises. Anson FP754 collided with Anson FP998.

DATE:

*12/1 PCL*

COMPOSITION:

*12/1 PCL / 12/1*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~26. Collision in the air.~~

*21 Collision - A/C.*

*21*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(A) Grounded for one month. 48-hour passes stopped for same period, coupled with fatigue duties when not required for ground School instruction. Endorsement of Log Book "Gross Carelessness".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Pilot of Anson FP754 failed to keep position in turn. Aircraft flying too close in formation. Gross carelessness.~~

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_