6	\$0 59 50 50 50 10 10 10 10 10 10 10 10 10 10 10 10 10		-/-/-	//	50 49 4 25 5 4	8 47		#4 #3 # #0141110	2 41	1/	/ /		R. RECRENC	04/5.
ا ر	PILOT	0THERS	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		AIRFRAME FAILURE					ENGINE FAILURE				- V
E OF A.	UNIT 2 S.	.F.T.S. Ontario	сом.	C A U	ses o LACE Pendl		CCID	ENTS	DATE H.Q. F	22-1	-4 3		2200 3 -59	The H
	A/C TYPE Anse		# <i>></i>	N	。 83 59	Scon	CRASH CAT.	R	SE	ME		AY •	NIGHT	3 NEW
\dashv	Aus	NAME		RANK	No.	YTUG		INJU	RIES			SERI	OUS	'ه ∕ا -ا⊃ا
ЫZ	Lam	dfinnson, bert, C.A sey, P.A.		F/O	R71493 J7827 IC3317	P. Pas	Nil S. Nil Nil							E C OTH
OF ENGINE		is, G.L.			R165133		s. Nil					SERIA	AL,No.	
ТҮРЕ	TYPE A/F	No.	EXTENT OF DAMAG		PORT SERIAL	DAT	E	НО	URS FL					1 1 1/4
	& ENGINE Anson	8359	Serio		INO.		INS	T. NIGHT	ON T	YPE solo	DUAL	SOLO	LAST 6 MOS.	[] ⊣ <i>[</i> .&
ORY	Jacobs :	17448/179	98 NiL											E 0 47/6
CATEG	SIGNAL NO		UNIT NO. 8	DATE	сом.	No. & E	ATE	REPO	RT	F	LE		DATE	
2	7 21	23=1			TURE	0 F		IDENT	7. /	. / a		<u> </u>	74 /	70.70
7	ν/3/ν/ ε ν s	9 4 8	6 01	11 21	EI PI 5	1 91 (4) (8)	Z1 81 81	/ `/ */	15 55	EZ S	25 25 25 Z	92 (72 82 0, 0,	65 OE 0

DUTY ON WHICH ENGAGED: Mercy flight.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Undercarriage retracted. while taxiing preparatory to take-off.	DATE: COMPOSITION: TUC/UDL	D-14
- -	RECOMMENDATIONS:	
PRIMARY CAUSE: 33. Technical defect. 8. MG Hailure	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL.	
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Tochnical Bilure, II/C failed to Lock down.	RECORDE	DBY DATE
35 Up Defect	CHECKED	BY DATE

 $(f) \circ (f) \circ (f)$