

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Dual instruction. INVESTIGATING OFFICER DATE 28 Jan. /43 NATURE OF ACCIDENT AND STAGE OF FLIGHT: F/L. D.F.A.L. Fosbery, #32 SFTS. COMPOSITION: Aircraft spun into ground. LOC HOCA That in trying to turn towards another a/c, at present unknown, the pilot, P/O. Mortimer, spun RECOMMENDATIONS from a climbing turn with not Instructors should be taken amoung pilots of sufficient speed. more mature age. P/O. Mortimer was aged 20 years. PRIMARY CAUSE: A.O.C., #4 T.C., did not concur with recommendations. Recovery from a spin at insufficient altitude to gain control of a/c before it struck the ground. (A) DISCIPLINARY (B) TECHNICAL (C) OTHER CONCLUSIONS OF A.I.B. Unauthorized low flying of Instructor, with pupil, deliberately engaged in Lunauthorized and dangerous flying in & close to the circuit & flew his a/c so that it went out of control at such a low altitude that he was unable to recover before a/c hit ground. DATE Westigation being poor, handled are agreed with. A.OC. app 'tec' FL to Fosberry, as Inv. Officer which is not in accordance with C.A.P.100 Sect. 4 para. 200(2).