



DUTY ON WHICH ENGAGED:

Test of airframe and engine after inspection.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Towed to open water from crane by dinghy. Engine failed to start after a number of tries. Impossible to get a line aboard to be towed clear as water was too rough to allow dinghy to come near. A/C drifted into dock of cold storage.

DATE:

D-14

COMPOSITION:

700/YM/

RECOMMENDATIONS:

PRIMARY CAUSE:

57. Miscellaneous.

24 Prop. etc.

(24)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Low temperature caused engine to become too cold. Engine failed to start.

A/C cast adrift in rough water.

RECORDED BY

DATE

CHECKED BY

DATE