

## CASPIR Aircraft Accident Cards

---

**Serial:** 3628

**Title:** Fleet Fort serial:3628 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-January-18. Fleet Fort II s/n 3628. This accident involved 2 people. Ball JB, Decruyerfaere GM

**Keywords:** RCAF Fleet Fort II,3628,3 WS,3 Wireless School,Stevenson Field  
Winnipeg,1943-January-18,Ball,DecruyerfaereRCAF L20

**Created:** 1943-01-18

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3628>



DUTY ON WHICH ENGAGED:

Wireless training exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft struck fence at end of runway on forced landing after takeoff nosing up on propellor.

DATE:

D.14

COMPOSITION:

10/17-0

RECOMMENDATIONS:

PRIMARY CAUSE:

~~13. Engine failure~~

15 *Noce Land*

15

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Extreme cold weather.~~

~~Struck boundary fence of end of runway.~~

RECORDED BY

DATE

CHECKED BY

DATE