

· / / / / / / / / / / / / / / / / / / /	
Duty on which engaged: Navigation wings cross country.	OR COMMANDING OFFICER'S REPORT: D-14
) NATURE OF ACCIDENT AND STAGE OF FLIGHT: On arrival at base U/C failed to lower. Pilot used all means to lower U/C, A/C made belly landing.	D-14 DATE: COMPOSITION:
)	RECOMMENDATIONS:
) PRIMARY CAUSE: 33. Technical defect.) 8. Price Chrical	ACTION TAKEN:
))) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER Orders have been issued to the effect that U/C must be lowered and raised at least every half hour while operating in sub-zero conditions.
secondary cause or contributing factors: 34; Wheels up landing. 32. We refect: 3 5	Orders have been issued to the effect that U/C must be lowered and raised at least every half hour while