

CASPIR Aircraft Accident Cards

Serial: FE278

Title: North American Harvard Mk. IIB serial:FE278 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-02. Harvard II s/n FE278. This accident involved 1 person. Arnold

Keywords: RAFHarvard II,FE278,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-02,ArnoldRCAF L20

Created: 1943-04-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE278>

DUTY ON WHICH ENGAGED:

Night flying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot taxied A/C to apron in front of hangar and failed to see gasoline truck. A/C struck the truck with stbd mainplane.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

2. Hitting obstructions.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed. Action in accordance with T.C.I. (tr.) 3/16. Pilot put on charge for contravention of Flight Order. Awarded severe reprimand.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

17. Disobedience of standing orders.
24. Carelessness.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____