

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFI	CER)
I.F. instrument.	OR COMMANDING OFFICER'S REPORT:	n =17.)•
A/C failed to maintain height after	DATE: COMPOSITION:	D-14)
take - off, force landed, even though engine was running normally)
) & 38" of boost of applied.			ì
)	RECOMMENDATIONS:)
PRIMARY CAUSE: 59. Obscure. As take-off was made on wet runway; it is presumed water froze on surfaces of mainplanes, thereby upsetting airflow, resulting in insufficient lift. 15. Jauca Land.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OT:	HER)
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
, SESSMENT CAUSE ON CONTINUE THO PROTOKS.)
<i>)</i>		RECORDED BY DATE)
•			
		CHECKED BY DATE)
)