١٥٢	PILOT OTHERS		FRAME	FAIL		140/62			NE FA		
PE OF A	S.F.T.S. COM. #1 TC	A U S			ccide Line	NTS	DATE H.Q. F	11.4 LE 1	•43∥™® 300 <i>-</i> FE	1400 •762	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
7	A/C TYPE <b>Harvard I</b> IB	No.	FE.76	2	CRASH CAT. C.1		SE X	ME	DAY X	NIGHT	M HELLER
上	NAME	RANK	No.	DUTY		וענא	RIES		SE	ERIOUS	O DRY SUR
	Thomson, G.S.	ALA	F <b>X</b> 9090	OP P	Nil				FATA	L INJURY	C A U S E S
TYPE OF ENGIN		,								CARD RIAL NO.	S SYNG
ř	TYPE A/F No. EXTENT	REPO	RT SER!AL	DATE		но			Y PILOTS		1 1 / 8//
=	& ENGINE OF DAMAGE	slig			INST.	NIGHT	ON T	/PE SOLO	TOTAL DUAL SO	LAST SLO 6 MOS	
GORY	Wasp 20407/42/15044 Ni	L.									A G M QUISH
ATE	SIGNAL NO. & DATE UNIT NO. &	DATE	сом.	No. & D.	ATE	REPOS	RT.	FI	LE	DATE	]   K 🖔

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFIC	ER		)
) Flying training exercise.	OR COMMANDING OFFICER'S REPORT:			1
, , ,		D-14		,
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:		r.	)
A.T.S. pupil pilot flew into cable	COMPOSITION:	1.1.1.15		)
tow line. Due to bright sunlight,		7.00		,
sun screen used during 1st attack.		D-14 / V5		,
As attack was closed the drogue moved	1			)
into sight, it became obscured by	RECOMMENDATIONS:			<b>)</b> .
sun screen & collision occurred during	ng			
subsequent breakaway.				
PRIMARY CAUSE:				
26. Collision in the air.				.)
22 / 20				,
22. ballis was platmetton.	ACTION TAKEN:			,
$\vee$ ( $\lambda \mathcal{H}$	(A) DISCIPLINARY (B) TECHNICAL (C)	OTHER		)
	Log book endorsed "Error of	Judgment".		)
1				1
,				,
)				)
SECONDARY CAUSE OR CONTRIBUTING FACTORS:				)
32. Pilot error.		,		,
,		RECORDED BY	DATE	,
)				
) R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41		CHECKED BY	DATE	)
	_)_) ) ) ) ) ) ) ) )	) ) ) ) )	) ) ) )	) .