

CASPIR Aircraft Accident Cards

Serial: FE342

Title: North American Harvard Mk. IIB serial:FE342 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-14. Harvard II s/n FE342. This accident involved 1 person. Hall RA

Keywords: RAFHarvard II,FE342,41 SFTS,41 Service Flying Training School,R1 Halbrite,1943-April-14,HallRCAF L20

Created: 1943-04-14

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE342>

DUTY ON WHICH ENGAGED:

Training - steep turns.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While practicing steep turns engine began to run erratically. Pupil checked up, was unable to find reason and decided to land. On landing port tire burst causing wing tip to touch ground.

DATE:

COMPOSITION:

LUC UTB ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~1. Swinging on landing.~~

2. *Seewing.*

(2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~43. Fire trouble.~~

~~58. Precautionary landing.~~

37. *Tire Burst.*

(37)

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____