

CASPIR Aircraft Accident Cards

Serial: FE281

Title: North American Harvard Mk. IIB serial:FE281 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-April-16. They are: Harvard II s/n 2759, Harvard II s/n FE281. This accident involved 2 people. Stephen AD, Dodds H

Keywords: RAFHarvard II,FE281,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-16,Dodds,StephenRCAF L20

Created: 1943-04-16

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE281>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Routine training flight.

OR COMMANDING OFFICER'S REPORT:

D-14. ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

A/C swung slightly on landing, port brake grabbed swinging A/C in direction of U/S A/C parked off runway.

COMPOSITION:

Stbd. brake insufficient to straighten up so hard port brake applied and A/C swung into port wing of parked A/C.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~46. Brake failure.~~

Differences in brake clearances, also dust and grit in port brake causing binding.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

6. Collisions

(6)

NIL.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~45. Collision.~~

36. Brake Failure

(36)

RECORDED BY

DATE

CHECKED BY

DATE