Įų	-	l = l				AIRFRAME FAILURE ENGIN							JE FAILURE PAIN			
PE OF A	UNIT #33 A.M.S. COM. Mount Hope, Ont. #2 T.G.				PL.	uses of accider PLACE 3 miles east of Themesford, Ontario									HLHO'L	
F	1	A/C TYPE Anson 1			No	no. 7050		CRASH CAT. A		SE			DAY NIGHT		S WELL	
十	╞				ANK	NO. DUTY INJURIES					SERIOUS >					
ENGINE		Parker, H.D. Scripton, D.W. LAG Quinn, U.J. LAG Briney, J. LAG Cunnington, J.A. LAG			AC AC	C 1399715 NAV.(C 538203 AB (P)			Dangerously -Died			ed FAT		4 m	Z OTHER O	
PE OF EN														>. 	PRINTS	
ТҰ		TYPE A/F & ENGINE				RT SERIAL	DATE		НО	URS FL	JRS FLOWN BY P		ILOTS		1 1/8//	
	<u> </u>	Anson	<i>]</i> 7050	OF DAMAGE Totally	FOR			INST.	NIGHT	ON T		TOTA DUAL S	L LA	ST T	- \\ \\ \\ \\ \\ \	
GORY		Cheetah	IX 1772 1760	91/AS3177 94/AS3057	2 I 5 I	otally								- G Н 1	C CYCY	
λTΕ		SIGNAL No. 8	& DATE	UNIT No. & DA	TE	сом.	No. & DAT	ε	REPO	२ Т	FIL	E	DATE	=	7 ST. 48	

DUTY ON WHICH ENGAGED: Night navigational exercise. COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

INVESTIGATING OFFICER'S FEFORT

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Whilst on a night navigational detail, COMPOSITION: pilot flew into snowstorm, decided to S/L McLar

pilot flew into snowstorm, decided to turn back towards London aerodrome. During turn to left, port wing struck

ground and A/C crashed.

PRIMARY CAUSE:

20 Flw into Fraguet

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

32. Pilot error

1406 /PSI/WUM

S/L McLaren, R.D., #31 A.N.S. Port Albert.

ECOMMENDATIONS

DATE: 7-4-43.

No reasonable recommendation can be made. A high percentage of A.N.S. pilots are inexperienced. A certain element of risk as to weather must be taken or training would be seriously curtailed. More I.F. and if

possible more stress laid on cloud flying at S.F.T.S

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER Mil.

CONCLUSIONS OF A.I.B.

A/C crashed on routine night navigation air exercise due to poor airmans ip on the part of the staff pilot) who although experienced on Anson A/C, was inexperienced on type of flying. Filot erred in attempting to fly contact when snow showers were encountered and then neglected to pay attention to his altimeter when descending. It is considered that this pilot's instrument flying practice had been neglected, in the past.

CHECKED BY

DATE

R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41