				RAME		CHILL COM MONTH		S. STS. STE			SE SERVE
A/C	PILOT OTHERS	CAUSES OF ACCIDENTS								^	H, 1, 10 0
PE OF	Rockcliffe, Ont. #3 TC			Rockcliffe				DATE 10.4.4\$TIME 0825			M ME THER
ŽΕ	TYPE Amson II		No.	7161		CRASH CAT. C.1	SE	ме Х	X X	NIGHT	
上	NAME	RAN	K	No.	DUTY	ענאו	RIES		SERIC		[ ] ( suf
	Grant D.A.	F.	S. R	.88204	P	Nil			FATAL	V YRULNI	.1" V 🕸 /
E OF ENGINE								•	CAR SERIAL		O JAO CRIMACI
杜	TYPE A/F NO EXTENT		REPORT	TSERIAL	<u></u>	_ н	HOURS FLOWN BY P				1/0//
	& ENGINE No. OF		FORM	No.	DAT	INST. NIGHT	ON TY	PE	TOTAL	LAST	S JAME OFF
	Anson II #7161	NiL.				1431. 141011	DUAL	SOLO DU	L SOLO	6 MOS	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1.	Jacobs 17206/3385						-				A CHICAT
GORY	17245/3424	Both pro	opel	lors	roke	n.				-	
1		IIT No. & DA	TE	COM.	No. & I	DATE REPO	ORT_	FILE	ים .	ATE	
\ \	5 A.415 10.4.43										

-	<b>, , , , , , , , , , , , ,</b> , , , , , ,
DUTY ON WHICH ENGAGED: Running engines prior to takeoff	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: D-14
While testing engines prior to take off, pilot opened both throttles at once and did not hold control column back causing	DATE: COMPOSITION: TM/NN/PCM
A/C to nose up.	RECOMMENDATIONS:
PRIMARY CAUSE: 24. Carelessness. /6. Others	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Log book endorsed "Carelessness".
SECONDARY CAUSE OR CONTRIBUTING FACTORS:  Nosing up:	RECORDED BY DATE
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE